




1

FURNITURE SETTING




WITH THE ADDITION OF THE TURN LIMITER THE FURNITURE IS SET FROM 3582 SYNERGY MORTICE LOCK TO SUIT 3782 SELECTOR MORTICE LOCK.



FURNITURE READY FOR 3782 SELECTOR MORTICE LOCK.

2


3582 SYNERGY SETTING



TURN LIMITER IS NOT INSTALLED.

3

3782 SELECTOR SETTING



TURN LIMITER

TURN LIMITER INSTALLED.